OEM Guide Page
HWH SpaceMaker Equipment for TAZWELL COACHES Vehicles

(File: MR407350.DOC | Revised: 26APR17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP20614* *AP20615*	**VERTICAL ARM ROOM EXTENSION – 36.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP20613 KIT** **SEE > MR412500.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91348 (14.30″ STROKE) REPLACES AP19378 SYNCHRONIZING CYLINDER_____ ITEM 6 – RAP90726 (5.75″ STROKE) REPLACES AP15042 TUBE KIT_____ RAP91223- REPLACES AP19936 HOSE ASSEMBLIES_____ ITEM 4 – RAP49245 (AP49245) ITEM 5 – RAP49245 (AP49245)
MECHANISM *AP26333* *AP26334*	**VERTICAL ARM ROOM EXTENSION – 24.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP26332 KIT** **SEE > MR412500.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 - RAP91200 (10.172″ STROKE) REPLACES AP24733 SYNCHRONIZING CYLINDER_____ ITEM 6 - RAP91019 (3.935″ STROKE) REPLACES AP13180 TUBE KIT_____ RAP91224- REPLACES AP23196 HOSE ASSEMBLIES_____ ITEM 4 - RAP24643 (AP24643) ITEM 5 - RAP24642 (AP24642)