OEM Guide Page
HWH SpaceMaker Equipment for TRIVAN TRUCK BODY Vehicles

(File: MR408300.DOC | Revised: 08MAY17)

> Printable PDF File

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM *AP19281* *AP19282*	**FOUR CYLINDER ROOM EXTENSION – 70.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP46339 KIT** **SEE > MR412006.HTML FOR DRAWING AND PARTS INFORMATION.** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91189 (71.0″ STROKE) REPLACES AP17270 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP92916 (13.730″ STROKE) REPLACES AP46340 **SEE > MR418004.HTML _____ FOR ADD'L SYNC. CYL. REPLACEMENT PARTS.** TUBE KIT_____ ITEM 2 – RAP91221 – REPLACES AP17321
MECHANISM *AP26043*	**FLOOR CYLINDER LIFT – 10.172" STROKE – AP46460 KIT** CYLINDER ASSEMBLY_____ RAP91347 (10.172″ STROKE)-REPLACES AP26043
MECHANISM *AP26889* *AP26890*	**DUAL CYLINDER ROOM EXTENSION 36.0" STROKE (WITH SYNCHRONIZING CYLINDER)** **AP39048 KIT** **SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION** CYLINDER ASSEMBLY_____ ITEM 1 – RAP91799 (36.5″ STROKE) REPLACES AP23577 SYNCHRONIZING CYLINDER_____ ITEM 3 – RAP90474 (14.630″ STROKE) REPLACES AP12484 TUBE KIT_____ ITEM 2 – RAP90480 – REPLACES AP13252