

# OEM Guide Page

## HWH SpaceMaker Equipment for **EURO CONVERSIONS INC. Vehicles**

(File: MR401750.DOC | Revised: 07SSEP17)

[> Printable PDF File](#)

**PROCEDURE:**

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements .
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> <i>AP2331</i>	<b>DUAL CYLINDER ROOM EXTENSION – 47.0” STROKE – 4” TUBES  (WITH RACK SENSING VALVE)  SEE &gt; <a href="#">MR411534.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90108 (47.0” STROKE) REPLACES AP2194 HOSE ASSEMBLIES_____ ITEM 7 - RAP4159 (AP4159) ITEM 8 - RAP4060 (AP4060) ITEM 9 - RAP4060 (AP4060) ITEM 10- RAP4159 (AP4159)
<b>MECHANISM</b> <i>AP2382</i>	<b>SINGLE CYLINDER ROOM EXTENSION - 45.0” STROKE – AP10461 KIT  SEE &gt; <a href="#">MR411000.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90105 (45.0” STROKE) REPLACES AP2486 TUBE KIT_____ ITEM 2 - RAP90102 - REPLACES AP2485
<b>MECHANISM</b> <i>AP2488</i>	<b>DUAL CYLINDER ROOM EXTENSION – 31.0” STROKE – 4” TUBES  (WITH RACK SENSING VALVE)  SEE &gt; <a href="#">MR411534.HTML</a> FOR DRAWING AND PARTS INFORMATION</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90109 (31.0” STROKE) REPLACES AP2490 HOSE ASSEMBLIES_____ ITEM 7 - RAP4159 (AP4159) ITEM 8 - RAP4059 (AP4059) ITEM 9 - RAP4059 (AP4059) ITEM 10- RAP4159 (AP4159)