
OEM Guide Page

HWH SpaceMaker Equipment for **QUALITY VANS Vehicles**

(File: MR405730.DOC | Revised: 21APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms

MECHANISM
AP22093

FOUR CYLINDER CANOPY LIFT – 38.5” STROKE (WITH SYNCHRONIZING CYLINDER)
AP45710 KIT

CYLINDER ASSEMBLY _____ RAP91700 (38.5” STROKE) – REPLACES AP22093
SYNCHRONIZING CYLINDER _____ RAP92915 (15.455” STROKE)–REPLACES AP43906
SEE > [MR418004.HTML](#) FOR ADDITIONAL SYNC CYLINDER REPLACEMENT PARTS