



<b>MECHANISM</b> AP44654 AP44655	<b>DUAL CYLINDER ROOM EXTENSION – 34.5” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP44653 KIT</b> <b>SEE &gt; <a href="http://MR412005.HTML">MR412005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90464 (14.010” STROKE) REPLACES AP14368 <b>OR</b> RAP93556 (12.140” STROKE) REPLACES AP49062 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
<b>MECHANISM</b> AP51686	<b>CYLINDER ASSEMBLY 25.5” STROKE</b> CYLINDER ASSEMBLY_____ RAP93555 (25.5” STROKE)-REPLACES AP51686
<b>MECHANISM</b> AP53194 AP53195	<b>DUAL CYLINDER ROOM EXTENSION – 25.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP53096 KIT</b> <b>SEE &gt; <a href="http://MR412005.HTML">MR412005.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP90488 (35.0” STROKE) REPLACES AP15224 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90440 (10.095” STROKE) REPLACES AP16509 <b>OR</b> RAP93573 (8.78” STROKE) REPLACES AP52155 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252