

# OEM Guide Page

## HWH SpaceMaker Equipment for **STERLING COACH** Vehicles

(File: MR407050.DOC | Revised: 26APR17)

> [Printable PDF File](#)

### PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

<b>SLIDE-OUT Mechanisms</b>	
<b>MECHANISM</b> AP30637 AP30638	<b>DUAL CYLINDER X-SLIDE – 30.75” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP34101 KIT</b> <b>SEE &gt; <a href="#">MR412670.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP91352 (13.90” STROKE) REPLACES AP27513 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90725 (5.460” STROKE) REPLACES AP15043 TUBE KIT_____ ITEM 2 - RAP91229 - REPLACES AP27587 HOSE ASSEMBLIES_____ ITEM 4 - RAP24627 (AP24627) ITEM 5 - RAP24627 (AP24627)
<b>MECHANISM</b> AP38251 AP38252	<b>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP39999 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP38900 AP38901	<b>UNIVERSAL STRAIGHT OUT – 24.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP40531 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
<b>MECHANISM</b> AP39645 AP39646	<b>UNIVERSAL STRAIGHT OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP40532 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)

<b>MECHANISM</b> AP40006 AP40007	<b>UNIVERSAL STRAIGHT OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER)</b> <b>AP39996 KIT</b> <b>SEE &gt; <a href="#">MR412685.HTML</a> FOR DRAWING AND PARTS INFORMATION.</b>  CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
--	---