

OEM Guide Page

HWH SpaceMaker Equipment for **SVI TRUCKS** Vehicles

(File: MR407260.DOC | Revised: 21MAY19)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP38944</i> <i>AP38945</i>	<p>UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP40346 AND AP42509 KITS SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072</p> <p>LIFT CYLINDER ASSEMBLY_____ ITEM 11 - REPLACES AP38604(2.75” LIFT) RAP92260 SHORT W/90deg.fitting RAP92260-01 LONG W/90deg.fitting RAP92260-02 45 deg. fitting</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881</p> <p>LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>
MECHANISM <i>AP43166</i> <i>AP43167</i>	<p>UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP51232 SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP93303 (10.540” STROKE) REPLACES AP46064</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>

SLIDE-OUT “PLATFORM LIFT” Mechanisms	
MECHANISM <i>AP51183 (126 1/4”)</i>	<p>PLATFORM LIFT THREE-CYLINDER SEE > MR414010.HTML FOR DRAWING AND PARTS INFORMATION.</p> <p>CYLINDER W/SEQ. VALVE ASSY___ ITEM 1 - RAP93139 (4.8” STROKE) REPLACES AP44387</p> <p>CYLINDER ASSEMBLY_____ ITEM 2 - RAP93140 (4.8” STROKE) REPLACES AP44395</p>