

OEM Guide Page

HWH SpaceMaker Equipment for **TALEN CARROSSERIEBOUW** Vehicles

(File: MR407325.DOC | Revised: 26APR17)

> [Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms

MECHANISM

AP19281

AP19282

DUAL CYLINDER ROOM EXTENSION – 70.0” STROKE (WITH SYNCHRONIZING CYLINDER)

AP37139 KIT

SEE > [MR412006.HTML](#) FOR DRAWING AND PARTS INFORMATION.

CYLINDER ASSEMBLY_____	ITEM 1	- RAP91189	(71.0” STROKE)
		REPLACES	AP17270
SYNCHRONIZING CYLINDER_____	ITEM 3	- RAP91809	(26.860” STROKE)
		REPLACES	AP17246
TUBE KIT_____	ITEM 2	- RAP91221	- REPLACES AP17321