

OEM Guide Page

HWH SpaceMaker Equipment for **TURN KEY INDUSTRIES** Vehicles

(File: MR408375.DOC | Revised: 21MAY19)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements.
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms	
MECHANISM <i>AP38251</i> <i>AP38252</i>	UNIVERSAL STRAIGHT OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP42609 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>
MECHANISM <i>AP38383</i> <i>AP38384</i>	UNIVERSAL LEVEL OUT – 26.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP40434 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. <p>CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072</p> <p>LIFT CYLINDER ASSEMBLY_____ ITEM 11 - REPLACES AP38604(2.75” LIFT) RAP92260 SHORT W/90deg.fitting RAP92260-01 LONG W/90deg.fitting RAP92260-02 45 deg. fitting</p> <p>SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92469 (9.130” STROKE) REPLACES AP39275</p> <p>LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264</p> <p>TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267</p> <p>HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)</p>
MECHANISM <i>AP38944</i> <i>AP38945</i>	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP40774 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION.

CYLINDER ASSEMBLY_____	ITEM 1	- RAP92076 (30.5" STROKE)
		REPLACES AP38072
LIFT CYLINDER ASSEMBLY_____	ITEM 11	- REPLACES AP38604(2.75" LIFT)
		RAP92260 SHORT W/90deg.fitting
		RAP92260-01 LONG W/90deg.fitting
		RAP92260-02 45 deg. fitting
SYNCHRONIZING CYLINDER_____	ITEM 3	- RAP92077 (10.540" STROKE)
		REPLACES AP37881
LIFT SYNCHRONIZING CYLINDER_	ITEM 12	- RAP92316 - REPLACES AP38264
TUBE KIT_____	ITEM 2	- RAP92079 - REPLACES AP38267
HOSE ASSEMBLIES_____	ITEM 4	- RAP24632 (AP24632)
	ITEM 5	- RAP24638 (AP24638)

MECHANISM AP40822 AP40823	UNIVERSAL STRAIGHT OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP47756 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92075 (20.5” STROKE) REPLACES AP39251 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP92092 - REPLACES AP39321 HOSE ASSEMBLIES_____ ITEM 4 - RAP24631 (AP24631) ITEM 5 - RAP24637 (AP24637)
MECHANISM AP44727 AP44728	UNIVERSAL LEVEL OUT – 20.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP42188 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - REPLACES AP38604(2.75” LIFT) RAP92260 SHORT W/90deg.fitting RAP92260-01 LONG W/90deg.fitting RAP92260-02 45 deg. fitting SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92316 - REPLACES AP38264 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)