

OEM Guide Page

HWH SpaceMaker Equipment for **VAN AMERICA / ROCKWOOD Vehicles**

(File: MR408600.DOC | Revised: 09MAY17)

[> Printable PDF File](#)

PROCEDURE:

1. Locate the HWH identification tag on the SpaceMaker mechanism to get the correct mechanism part number.
2. Find the correct SpaceMaker mechanism part number in the left column below.
3. Refer to the listed HWH Parts Manual Page for general replacement parts information and item number arrangements .
4. Note that two-cylinder mechanisms with a synchronizing cylinder have two part numbers. One number is for the left assembly and one is for the right assembly. If the mechanism assembly originally had one number, that number is listed with the new numbers.

SLIDE-OUT Mechanisms

MECHANISM
AP10378

DUAL CYLINDER ROOM EXTENSION – 39.0” STROKE (WITH RACK SENSING VALVE)
AP10560 KIT
SEE > [MR411530.HTML](#) FOR DRAWING AND PARTS INFORMATION.

CYLINDER ASSEMBLY_____	ITEM 1 - RAP90007 (39.0” STROKE)
	REPLACES AP1700
HOSE ASSEMBLIES_____	ITEM 7 - RAP4073 (AP4073)
	ITEM 8 - RAP2446 (AP2446)
	ITEM 9 - RAP2445 (AP2445)
	ITEM 10- RAP16172 (AP16172)