

MECHANISM AP19974 AP19975	DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 16.0” STROKE (WITH SYNC. CYL.) AP19973 KIT NO INFORMATION AVAILABLE.
MECHANISM AP20554 AP20555	DUAL CYLINDER “HAT” ROOM EXTENSION – 16.0” STROKE (WITH SYNC. CYLINDER) AP20553 KIT SEE > MR412050.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90643 (16.5” STROKE) REPLACES AP17473 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90644 (6.390” STROKE) REPLACES AP17436 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP21482 AP21483	DUAL CYLINDER “HAT” ROOM EXTENSION – 31.0” STROKE (WITH SYNC. CYLINDER) AP21476 KIT SEE > MR412050.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90457 (31.5” STROKE) REPLACES AP15738 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90442 (12.57” STROKE) REPLACES AP16484 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP24857 AP24858	DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 31.0” STROKE (WITH SYNC. CYL.) AP24364 KIT SEE > MR412200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91199 (32.0” STROKE) REPLACES AP24262 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90466 (12.980” STROKE) REPLACES AP14301 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587
MECHANISM AP27483 AP27484	DUAL CYLINDER LEVEL OUT ROOM EXTENSION – 31.0” STROKE (WITH SYNC. CYL.) AP27482 KIT SEE > MR412200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91199 (32.0” STROKE) REPLACES AP24262 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90442 (12.570” STROKE) REPLACES AP16484 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587
MECHANISM AP33254 AP33255	DUAL CYLINDER ROOM EXTENSION – 29.125” STROKE (WITH SYNCHRONIZING CYL.) SEE > MR412020.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90689 (32.0” STROKE) REPLACES AP19616 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90690 (11.780” STROKE) REPLACES AP17966 TUBE KIT_____ ITEM 2 - RAP91222 - REPLACES AP19736
MECHANISM AP33429 AP33430	DUAL CYLINDER ROOM EXTENSION – 16.0” STROKE (WITH SYNCHRONIZING CYL.) AP33428 KIT SEE > MR412020.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91607 (17.0” STROKE) REPLACES AP33519 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90644 (6.390” STROKE) REPLACES AP17436 TUBE KIT_____ ITEM 2 - RAP90658 - REPLACES AP18428

MECHANISM AP33776	DUAL CYLINDER ROOM EXTENSION – 31.0” STROKE (WITH SYNCHRONIZING CYL.) AP34108 KIT SEE > MR412200.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91199 (32.0” STROKE) REPLACES AP24262 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90442 (12.570” STROKE) REPLACES AP16484 TUBE KIT_____ ITEM 2 - RAP91024 - REPLACES AP26587
MECHANISM AP35843	CYLINDER ASSEMBLY – 26.0” STROKE CYLINDER ASSEMBLY_____ RAP92523 (26.0” STROKE)-REPLACES AP35843
MECHANISM AP39182 AP39183	UNIVERSAL STRAIGHT OUT – 18.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41598 KIT SEE > MR412685.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92369 (6.30” STROKE) REPLACES AP39267 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP40528 AP40529	DUAL CYLINDER “HAT” ROOM EXTENSION – 24.0” STROKE (WITH SYNC. CYLINDER) AP40527 KIT SEE > MR412050.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90484 (24.5” STROKE) REPLACES AP15252 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92275 (8.420” STROKE) REPLACES AP39271 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP40753 AP40754	UNIVERSAL LEVEL OUT – 30.0” STROKE (WITH SYNCHRONIZING CYLINDER) AP41597 KIT SEE > MR412690.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92076 (30.5” STROKE) REPLACES AP38072 LIFT CYLINDER ASSEMBLY_____ ITEM 11 - RAP92261 (3.50” LIFT) REPLACES AP40746 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 LIFT SYNCHRONIZING CYLINDER_ ITEM 12 - RAP92503 - REPLACES AP40832 TUBE KIT_____ ITEM 2 - RAP92079 - REPLACES AP38267 HOSE ASSEMBLIES_____ ITEM 4 - RAP24632 (AP24632) ITEM 5 - RAP24638 (AP24638)
MECHANISM AP43112 AP43113	DUAL CYLINDER ROOM EXTENSION – 29.125” STROKE (WITH SYNCHRONIZING CYL.) AP33253 KIT SEE > MR412020.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92524 (30.125” STROKE) REPLACES AP43107 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP90690 (11.780” STROKE) REPLACES AP17966 TUBE KIT_____ ITEM 2 - RAP90658 - REPLACES AP18428

MECHANISM AP43994 AP43995	DUAL CYLINDER "HAT" ROOM EXTENSION – 22.0" STROKE (WITH SYNC. CYLINDER) AP43993 KIT SEE > MR412050.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP90593 (22.5" STROKE) REPLACES AP15384 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92522 (7.710" STROKE) REPLACES AP43403 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
--	--

STEP Systems	
AP37334	STEP COVER CYLINDER ASSEMBLY – 26.0" STROKE OBSOLETE – REPLACED BY AP39433
AP39433	STEP COVER CYLINDER ASSEMBLY – 26.0" STROKE SEE > MR415000.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92109 (26.0" STROKE) REPLACES AP39433 HOSE ASSEMBLY_____ ITEM 2 - RAP4217 (AP4217)