

MECHANISM AP45905 AP45906	DUAL CYLINDER ROOM EXTENSION – 18.0” STROKE (WITH SYNCHRONIZING CYL.) AP45882 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92921 (23.875” STROKE) REPLACES AP45903 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92369 (6.300” STROKE) REPLACES AP39267 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP47442 AP47443	DUAL CYLINDER ROOM EXTENSION – 20.0” STROKE (WITH SYNCHRONIZING CYL.) AP47441 KIT SEE > MR412005.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP92922 (25.875” STROKE) REPLACES AP47464 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92099 (7.010” STROKE) REPLACES AP39221 TUBE KIT_____ ITEM 2 - RAP90480 - REPLACES AP13252
MECHANISM AP50953 AP50954	DUAL CYLINDER ROOM EXTENSION – 30.0” STROKE (WITH SYNCHRONIZING CYL.) AP50952 KIT SEE > MR412011.HTML FOR DRAWING AND PARTS INFORMATION. CYLINDER ASSEMBLY_____ ITEM 1 - RAP91239 (45.0” STROKE) REPLACES AP24107 SYNCHRONIZING CYLINDER_____ ITEM 3 - RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ ITEM 2 - RAP90481 - REPLACES AP15379
MECHANISM AP52274 AP52275	THREE CYLINDER ROOM EXTENSION – 39.5” STROKE (WITH SYNCHRONIZING CYL.) AP52211 KIT CYLINDER ASSEMBLY_____ RAP91239 (40.5” STROKE) REPLACES AP24107 SYNCHRONIZING CYLINDER_____ RAP91018 (16.175” STROKE) REPLACES AP24085 TUBE KIT_____ RAP90481- REPLACES AP15379 MANUAL RETRACT SCREW_____ RAP93516- REPLACES AP52270
MECHANISM AP52276 AP52277	THREE CYLINDER ROOM EXTENSION – 30.5” STROKE (WITH SYNCHRONIZING CYL.) AP52212 KIT CYLINDER ASSEMBLY_____ RAP92920 (41.0” STROKE) REPLACES AP45561 SYNCHRONIZING CYLINDER_____ RAP92077 (10.540” STROKE) REPLACES AP37881 TUBE KIT_____ RAP90481- REPLACES AP15379 MANUAL RETRACT SCREW_____ RAP93516- REPLACES AP52270